



# WELD ANCHOR


# HAS<sub>Type</sub>




Drill hole proper diameter.



Clean hole and insert anchor with plug inside.



Insert ANCHOR use hammer to drive tapered insert.



ANCHOR is set and ready

The anchor itself can be welded for installation of various metals.

## HAS-TYPE Carbon Steel

Product No.	mm			kgf		Depth of Embedment
	D	L	Drill Bit	Pull Out Ultimate	Shear Load	
HAS-1045	10.0	45	11.0	850	670	30
HAS-1055	10.0	55	11.0	1,250	750	40
* HAS-1060	10.0	60	11.0			

\* Made to order

Concrete compressive strength 210 kgf/cm<sup>2</sup>

